

Current Firmware Revision: 1.02.0010

The following notes provide the revision history and a list of known firmware issues in the current release. For more information, please call your Extron Application Engineer.

Updated: March 24, 2015

Extron Products Affected: Annotator 300

TECH NOTES

Firmware upload – During the firmware upload, the unit will not respond to front panel or remote control changes. The upload process will take 5 minutes. During this upload time, the LCD will state “Firmware Loading” and the unit will be unresponsive. Do not remove power during the firmware upload process.

Firmware upgrade instructions – Please refer to the user manual for detailed instructions on updating the firmware on the Annotator 300. The manual is available on the Annotator 300 product page at www.extron.com.

Updated supported USB Device(s) in the firmware – Please refer to the Annotator 300 Compatibility List for details on which module(s) are now built into the firmware on the Annotator 300. The Annotator 300 Compatibility List is available on the Annotator 300 product page at www.extron.com.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES	EUROPE	ASIA	MIDDLE EAST
+800.633.9876 Inside USA/Canada	+800.3987.6673 Inside Europe	+800.7339.8766 Inside Asia	+971.4.2991800
+1.714.491.1500	+31.33.453.4040	+65.6383.4400	

KNOWN ISSUES

The following is a list of known firmware issues found in the Annotator 300 Version 1.02.0010

Issue (originated in v1.01.0003) – Image captured immediately after a reset cannot be recalled – If an image is captured immediately after a factory reset, it currently cannot be recalled. To resolve this state, power cycle the unit and all subsequent captures can be recalled without issue.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES	EUROPE	ASIA	MIDDLE EAST
+800.633.9876 Inside USA/Canada	+800.3987.6673 Inside Europe	+800.7339.8766 Inside Asia	+971.4.2991800
+1.714.491.1500	+31.33.453.4040	+65.6383.4400	

FIRMWARE RELEASE HISTORY

Released Version: 1.02.0010

Affects: **Firmware Revision:** 1.01.0003 and prior
Date: Units shipped prior to March 24, 2015

The following is a list of changes and fixes in this release.

Fixed Issue (originated in v1.01) –Annotator 300 output muted – After a large number of input resolution changes on the HDMI input, the Annotator 300 output would intermittently mute its output and the front panel would become unresponsive. This issue has been resolved.

Fixed Issue (originated in v1.01) – Screen saver does not affect DTP output – The DTP output was not disabled when the screen saver activated. This issue has been resolved.

Fixed Issue (originated in v1.01) – Embedded digital audio is sometimes muted after an input switch – Intermittently, the embedded audio on the HDMI and DTP outputs would be muted after multiple input switches. This issue has been resolved.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES	EUROPE	ASIA	MIDDLE EAST
+800.633.9876 Inside USA/Canada	+800.3987.6673 Inside Europe	+800.7339.8766 Inside Asia	+971.4.2991800
+1.714.491.1500	+31.33.453.4040	+65.6383.4400	

FIRMWARE RELEASE HISTORY

Released Version: 1.01.0003
Affects: **Firmware Revision:** 1.00
Date: Units shipped prior to November 11, 2014

The following is a list of changes and fixes in this release.

Fixed Issue (originated in v1.00) – Annotator 300 boot failure – On rare occasion the Annotator 300 would fail to boot properly, and would require being sent back to the factory for repair. This issue has been resolved.

Fixed Issue (originated in v1.00) – Incorrect output sync polarity – Some output rates included incorrect horizontal and vertical sync polarity values. All output rates have been updated to match VESA/SMPTE/CEA standards.

Fixed Issue (originated in v1.00) – OSD menu is incorrectly positioned for certain output rates – When the output rate is set to 2K or to a custom output rate, the OSD menu would be incorrectly positioned to the center of the output. This issue has been resolved.

Fixed Issue (originated in v1.00) – EDID cannot be captured from downstream device connected on DTP output – The firmware has been updated to allow the EDID from the downstream device on the DTP output to be captured. This issue has been resolved.

Added Feature – Ability to set the number of copies per print job – Firmware v1.01.0003 now supports the ability to set the amount of copies that will be printed when a print occurs. Reference manual for SIS commands.

Added Feature – Support for Daylight Savings – Firmware v1.01.0003 now supports the ability to set Daylight Savings. Reference manual for SIS commands.

Added Feature – Support for Backup and Restore– Firmware v1.01.0003 now supports the ability to backup/restore the box configuration. Reference manual for SIS commands.

Added Feature – Support for Caps Lock function on keyboard– Firmware v1.01.0003 now supports the Caps Lock function on the Keyboard.

Improved Feature (originated in v1.00) – Improved detection of large quantity of USB devices – Updated USB enumeration method and USB communication to support up to 25 USB devices.

Worldwide Sales Offices

Anaheim • Raleigh • Silicon Valley • Dallas • Chicago • New York • Washington, DC • Toronto • Mexico City • Paris • London • Frankfurt
Amersfoort • Moscow • Dubai • Johannesburg • New Delhi • Bangalore • Singapore • Seoul • Shanghai • Beijing • Tokyo

UNITED STATES	EUROPE	ASIA	MIDDLE EAST
+800.633.9876 Inside USA/Canada	+800.3987.6673 Inside Europe	+800.7339.8766 Inside Asia	+971.4.2991800
+1.714.491.1500	+31.33.453.4040	+65.6383.4400	